

00862.021808.

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
	:	Examiner: Elizabeth Keaney
TOSHIHIKO MIYAZAKI ET AL.)	
	:	Group Art Unit: 2882
Appl. No.: 09/705,957)	
	:	
Filed: November 6, 2000)	
	:	
For: IMAGE FORMATION APPARATUS)	
	:	
U.S. Patent No.: US 6,879,096 B1)	
	:	
Issued: April 12, 2005)	December 30, 2008

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323


Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office
by telephone at (212) 218-2100. All correspondence should continue to be directed to our
address given below.

Respectfully submitted,

A handwritten signature in black ink, appearing to be 'F. DeLucia', written over a horizontal line.

Frank DeLucia
Attorney for Patentees
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
NY_MAIN 516278v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 1 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE [56] REFERENCES CITED

Foreign Patent Document, "1-1031332" should read --11-31332--.

COLUMN 4

Line 2, "Another" should read --¶ Another--.

COLUMN 6

Line 13, "insulate" should read --insulated--;

COLUMN 7

Line 41, "Kv" should read --kV--.

COLUMN 17

Line 51, "matters" should read --matter--.

COLUMN 18

Line 21, "508 FIG. 7" should read --508. ¶ FIG. 7--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 2 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

Line 47, "toward outside" should read --toward the outside of--.

COLUMN 24

Line 56, "is" should read --are--.

COLUMN 30

Line 32, "First," should read --¶ First,--;

Line 44, "40x2and" should read --40x2 and--;

Line 52, "spat-" should read --sput--; and

Line 65, "1022chaving" should read --1022c having--.

COLUMN 33

Line 3, "interferes" should read --interfere with--;

Line 34, "any" should read --with any--;

Line 48, "a" should be deleted; and

Line 60, "bombard" should read --bombards--.

COLUMN 34

Line 4, "bombard" should read --bombards--; and

Line 14, "by" should read --with by--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 3 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 36

Line 37, ".1041" should read --1041--;

Line 40, "is" should read --is,--; and

Line 41, "is" should read --are--.

COLUMN 37

Line 65, "pass" should read --passes--.

COLUMN 38

Line 12, "a" should read --for a--.

COLUMN 39

Line 49, "curvature," should read --curvatures,--; and

Line 63, "is" should read --are--.

COLUMN 40

Line 6, "inch" should read --inches--;

Line 45, "is" should read --are--; and

Line 47, "inch" should read --inches--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 4 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 41

Line 41, "First" should read --Frit--.

COLUMN 43

Line 2, "the" should read --of the--; and

Line 12, "inch in diagonal," should read --inches measured diagonally,--.

COLUMN 44

Line 12, "a conductive" should read --a conductive element--.

COLUMN 45

Line 41, "spattering" should read --sputtering--; and

Line 62, "grand" should read --ground--.

COLUMN 46

Line 18, "On one" should read --One--; and

Line 24, "material," should read --material that--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 5 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 47

Line 28, "small" should read --smaller--;
Line 41, "spattering" should read --sputtering--;
Line 43, "spattering" should read --sputtering--;
Line 45, "spattered" should read --sputtered--;
Line 47, "spattering" should read --sputtering--; and "titan" should read --titanium--;
Line 49, "spattering" should read --sputtering--;
Line 51, "Titan" should read --Titanium--; and
Line 65, "perform" should read --performing--.

COLUMN 48

Line 7, "spattering" should read --sputtering--;
Line 8, "spattered" should read --sputtered--;
Line 11, "spattered" should read --sputtered--;
Line 12, "Å)" should read --Å).--;
Line 13, "spattered" should read --sputtered--;
Line 26, "and" should be deleted; and
Line 58, "are" should read --area--.

COLUMN 49

Line 4, "when" should read --When--;
Line 15, "covered" should read --be covered--; and
Line 28, "spattering" should read --sputtering--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 6 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 51

Line 30, "resolving" should read --dissolving--.

COLUMN 54

Line 5, "are" should read --is--;

Line 46, "as not overlapping" should read --so as not to overlap--; and

Line 51, "sponding" should read --spondence--.

COLUMN 56

Line 21, "At the" should read --The--; and

Line 49, "are" should read --is--.

COLUMN 57

Line 4, "raise" should read --rise--; and

Line 20, "arch-shaped" should read --arc-shaped--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 7 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 58

Line 1, "which" should read --to which--;
Line 2, "a" should read --an--;
Line 11, "become" should read --becomes--;
Line 17, "by" should read --with by--;
Line 25, "arch-shaped" should read --arc-shaped--;
Line 30, "arch-shaped" should read --arc-shaped--;
Line 34, "become" should read --becomes--;
Line 49, "arch-" should read --arc---; and
Line 64, "With" should read --When--.

COLUMN 59

Line 10, "adhere" should read --adheres--; and
Line 56, "from" should read --an--.

COLUMN 60

Line 12, "cause" should read --causes--; and
Line 13, "arises" should read --to arise--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 8 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 61

Line 5, "are" should read --is--;
Line 7, "and" should read --which--;
Line 8, "the all" should read --all the--;
Line 11, "is" should read --are--;
Line 26, "non short circuit is not" should read --no short circuit is--; and
Line 27, "without" should be deleted.

COLUMN 62

Line 16, "an" should read --a--;
Line 36, "an" should read --a--;
Line 46, "like that," should read --to perform--;
Line 49, "past" should read --paste--;
Line 51, "form" should read --forms--;
Line 54, "an" should read --a--; and
Line 60, "The" should read --As regards--.

COLUMN 63

Line 9, "produce" should read --produces--; and
Line 22, "maintains" should read --maintain--.

COLUMN 64

Line 6, "an" should read --a--; and
Line 49, "siapoaws" should read --disposed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 9 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 65

Line 8, "solved" should read --dissolved--; and
Line 28, "Ω/ε" should read --Ω/□--.

COLUMN 66

Line 16, "benzonitrile" should read --Benzonitrile--; and
Line 32, "KV" should read --kV--.

COLUMN 67

Line 49, "Furthermore," should read --¶ Furthermore,--; and
Line 59, "past" should read --paste--.

COLUMN 69

Line 24, "electron" should read --electrons--; and
Line 33, "to" should be deleted.

COLUMN 74

Line 44, "shorted" should read --shorter--; and
Line 57, "3015." should read --3015'--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 10 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 75

Line 37, "3015." should read --3015'.--; and
Line 65, "Example" should read --(Example--.

COLUMN 76

Line 14, "denote an" should read --denote a--;
Line 45, "wiring" should read --wirings--; and
Line 46, "is" should read --are--.

COLUMN 78

Line 40, "member.3209" should read --member 3209--; and
Line 52, "satisfied" should read --satisfactory--.

COLUMN 81

Line 64, "this" should read --to this--.

COLUMN 82

Line 59, "Aluminum" should read --aluminum--.

COLUMN 83

Line 32, "Incidentally," should read --¶ Incidentally,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 11 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 84

Line 3, "are" should read --is--; and

Line 23, "an" should read --a--.

COLUMN 85

Line 15, "an" should read --a--; and

Line 54, "maybe" should read --may be--.

COLUMN 86

Line 12, "as" should read --as to be--;

Line 17, "as" should read --as to be--; and

Line 19, "an" should read --a--.

COLUMN 88

Line 38, "In as sealing materials" should read --Indium as a sealing material--; and

Line 40, "sealing materials," should read --a sealing material,--.

COLUMN 89

Line 15, "an" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 12 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 90

Line 57, "problem" should read --problem such that--.

COLUMN 91

Line 26, "occur" should read --occurs--;

Line 32, "but" should be deleted;

Line 43, "Incidentally," should read --¶ Incidentally,--; and

Line 47, "using." should read --to be used.--.

COLUMN 92

Line 47, "to" should read --to be--.

COLUMN 93

Line 4, "a" should be deleted; and

Line 48, "insides" should read --inside--.

COLUMN 94

Line 5, "becomes" should read --become--;

Line 38, "land" should read --1 and--; and

Line 58, "is" should read --are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 13 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 97

Line 13, "22th" should read --22nd--;
Line 36, "(23th)" should read --(23rd--; and
Line 63, "23th" should read --the 23rd--.

COLUMN 98

Line 37, "pyrolisis" should read --pyrolysis--;
Line 66, "are" should read --is--; and
Line 67, "23th" should read --the 23rd--.

COLUMN 99

Line 5, "stripes" should read --stripe--; and
Line 15, "23th" should read --the 23rd--.

COLUMN 100

Line 21, "Issue" should read --Issue 2--.

COLUMN 101

Line By, "" should read --¶ By--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 14 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 102

Line 2, "These" should read --The--;
Line 5, "Besides," should read --¶ Besides--;
Line 10, "electically" should read --electrically--; and
Line 16, "the anode-side potential specifying part," should be deleted.

COLUMN 103

Line 57, "vO" should read --v_o--.

COLUMN 104

Line 10, "an" should read --and--; and
Line 48, "inial" should read --initial--.

COLUMN 105

Line 59, "to" should be deleted.

COLUMN 106

Line 61, "is" should read --are--; and
Line 66, "therm-press" should read --thermo-press--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 15 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 107

Line 1, "ACE" should read --ACF--; and
Line 54, "these" should read --the--.

COLUMN 108

Line 8, "is" should read --are--;
Line 13, "therm-" should read --thermo---; and
Line 23, "plat" should read --plate--.

COLUMN 109

Line 9, "sides" should read --side--; and
Line 57, "one" should read --individual--.

COLUMN 110

Line 18, "the" (first occurrence) should be deleted.

COLUMN 111

Line 23, "The" should read --¶ The--;
Line 24, "so-called" should read --of so-called--;
Line 27, "following." should read --follows.--; and
Line 46, "rectangular" should read --rectangle--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 16 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 112

Line 1, "mission" should read --emission--; and
Line 59, "Apart" should read --A part--.

COLUMN 113

Line 37, "de" should read --be--.

COLUMN 115

Line 22, "likes." should read --like.--.

COLUMN 119

Line 16, "terminals." should read --terminal.--; and
Line 63, "an" should read --a--.

COLUMN 121

Line 3, "likes" should read --like,--;
Line 19, "the" should read --that--;
Line 24, "being" should be deleted; and
Line 31, "as to" should read --so as to--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 17 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 122

Line 2, "likes" should read --like--;
Line 5, "likes." should read --like.--;
Line 9, "52" should read --S2--; and
Line 22, "Off" should read --OFF--.

COLUMN 123

Line 3, "as" should read --the--;
Line 27, "the" should read --whether the--; and
Line 46, "as" should read --by--.

COLUMN 124

Line 12, "the Ie" should read --if the Ie--; and
Line 26, "On" should read --ON--.

COLUMN 125

Line 25, "as same" should read --in the same manner--;
Line 40, "field" should read --fields--; and
Line 54, "changing-the" should read --changing the--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 18 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 126

Line 1, "as same" should read --in the same manner--; and
Line 25, "being put in" should read --is put into a--.

COLUMN 127

Line 40, "and, for example" should read --and--.

COLUMN 128

Line 18, "likes." should read --like.--; and
Line 34, "as same" should read --in the same manner--.

COLUMN 129

Line 45, "using" should be deleted; and
Line 56, "procedure of" should read --procedures for--.

COLUMN 130

Line 3, "of" should read --that--;
Line 8, "such" should read --in such--;
Line 32, "likes." should read --like--;
Line 40, "configurations as the connection" should read --connection configurations--;
Line 41, "configuration" should be deleted; and
Line 45, "31th" should read --31st--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 19 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 131

Line 8, "capacitor" should read --capacitance--.

COLUMN 133

Line 7, "on the" should be deleted;
Line 12, "as to protect and prevent" should read --to protect--; and
Line 57, "temperature" should read --temperatures--.

COLUMN 134

Line 35, "302" should read --4302--.

COLUMN 135

Line 9, "as same" should read --in the same manner--;
Line 10, "the foregoing the first" should read --that of the foregoing--;
Line 22, "as" should read --so as--;
Line 53, "exclusive" should read --exclusively--; and
Line 65, "has" should read --have--.

COLUMN 136

Line 25, "immediate" should read --immediately--; and
Line 27, "immediate" should read --immediately--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 20 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 137

Line 61, "of that" should read --as that--.

COLUMN 138

Line 7, "emit" should read --emit an--; and

Line 58, "beside" should read --not corresponding to--.

COLUMN 139

Line 17, "in stead" should read --instead--;

Line 46, "As same as the" should read --In the same manner as that of--; and

Line 66, "of" should read --wherein--.

COLUMN 140

Line 13, "has" should read --have--; and

Line 16, "(named it as" should read --(designated as the--.

COLUMN 144

Line 20, "above describe" should read --the above-described--;

Line 35, "puts" should read --put--;

Line 38, "turn off" should be deleted; and

Line 39, "S200)." should read --S200) is turned off--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 21 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 145

Line 35, "minimum. Then" should read --minimum, and then it--;

Line 36, "5303)." should read --S303).--;

Line 37, "confirm" should read --confirms--;

Line 43, "require restarting" should read --initiate a restart process in order--; and

Line 54, "carried" should read --is caused to carry--.

COLUMN 147

Line 65, "the a" should read --a--.

COLUMN 148

Line 36, "likes." should read --like.--;

Line 41, "the image" should read --to the image--; and

Line 52, "purposed" should read --purposes--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 22 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 150

Line 13, "likes." should read --like.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,879,096 B1

DATED : April 12, 2005

INVENTOR(S) : TOSHIHIKO MIYAZAKI ET AL.

Page 23 of 22

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

FCBS_WS 516278v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,879,096 B1

No. of add'l. copies
@ 30¢ per page

